


REPORT

TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH - DEVELOPMENT - TESTING



14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
AREA CODE 714 • 730-6239
AREA CODE 213 • 225-1564
FAX 714 • 730-6462

CLIENT **Douglas Aircraft Company**
Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, CA 90846
SAMPLE Attention: Ron Fornator
Water from Stormdrain #001
Torrance Facility-First Quarter
INVESTIGATION P.O. Number: T & M 23465C

DATE **March 20, 1991**
RECEIVED **Jan. 30, 1991**
LABORATORY NO. **46255**

Quarterly Analysis as Required by NPDES Permit #CA0001414

RESULTS

A one gallon grab sample was taken from the stormdrain on January 30, 1991 by a representative of Truesdail Laboratories, Inc.

Field Data


Flow Rate, GPD 611
Temperature, °F 69
pH, Units (EPA 150.1) 8.0
Settleable Solids, ml/L/hr (EPA 160.5) ND <0.2

MILLIGRAMS PER LITER

<u>Parameter</u>	<u>Method</u>	<u>Detection Limit</u>	<u>Concentration</u>
Suspended Solids	EPA 160.2	4	ND
BOD	EPA 405.1	2	ND
Oil and Grease	EPA 413.1	6	30

Note: Client did not request Chromium for this quarter.
ND= Not detected, below detection limit.

Respectfully submitted,
TRUESDAIL LABORATORIES, INC.


Patty Wisneski, Project Mgr.
Water and Waste Laboratory

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.